

Report ID: 19,542,506 Version: 1 11 Jul 2019 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2003	Registration:	DSN562	Reg Expiry:	10 Jan 2020	Engine			
WoF Expiry:	15 Dec 2019	Odometer:	253,649 Kms	Good No:	19542506	Oil level	~		
VIN:	7A8H6070707200313	Next Service:	261000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	CCW/				W	Performance	~		
Key:	SC W	-0	SC W SC	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	scw bla			715	HIL	Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent	HID				세비	CV joints	~		
* = decals	sc 916			The		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W						Performance	~		
		Note: som	ne defects & blemishes	s may not be disc	laved in the diagram	Hand Brake		~	
Body Insp	pection Comments			,		Tyres (lowest observed tread	l d depth	•	25)
								mm	
						Right front		.0	mm
						Left rear			mm
						Right rear			mm
Conditions During Body Inspection: Dry						Spare	6.0 Min		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	j					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			
Interior Comments						Electrical / Accessories	~		
Good									
Seats						-	~		
Carpets	Good					Tail lights	v		
	Good					Indicators	~		<u> </u>
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
General (omments					Window winder FR	~		<u> </u>
General Comments Wheel alignment recommended					Window winder RL		~		
g.						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)		~	<u> </u>
						CD (basic test only)		~	
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Engine Tir	ming Mechanism	Timing	Chain			Remote locking			~
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Lvidence		ement. N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Chris Vanner Date: 05 Jul 2019									

I have read and understood this condition guide.

Name:

Signature: