

Report ID: 19,543,353 Version: 2 05 Jul 2019 Created:

Make:	Holden	Model:	Vectra	Body Style:	Sedan		Pass	Fail	N/A
Year:	2001	<b>Registration:</b>	DTW181	<b>Reg Expiry:</b>	29 Jul 2019	Engine	1	1	
WoF Expiry:	29 Oct 2019	Odometer:	179,695 Kms	Good No:	19543353	Oil level	~		
VIN:	W0L0JBF19YL520060	Next Service:	191000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and the	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	DSC	-0	sc sc	-161-	s w	Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		•
*=decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs SC SC SC W D W						Performance	~		
		Note: som		may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftura	) )
						Tyres (lowest observed tread depth of tyres)   Left front 6.0 mm			
								mm	
						Right front Left rear		.0	mm
						ı ————		.0	mm
Conditions During Body Inspection: Wet						Right rear 6.0 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Engine oil l	-	meemspeede	<u>eominents</u>			Suspension			
Engine on i	edKS					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
	-					Window winder FL		~	
Ganaral	-ommonts					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 18	30,000	Reversing camera			~
Inspected by: Chris Vanner Date: 04 Jul 2019									
Inspected by: Chris Vanner Date: 04 Jul 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....