



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,543,638
Version:	1
Created:	09 Jul 2019

Make:	Suzuki	Body Style:	Hatchback
Model:	Splash	VIN:	TSMEXB32S00310526
Year:	2009	Odometer:	42,981 Kms
Road Conditions During Test Drive:	Dry		

Electrical			30	Fuel Flap Release	✓	Cooling System			78	Under Carriage	Good	Exterior	
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79	Sun Roof Operation	•		
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good		
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good		
4	High Stop Light	✓	Transmission and Drive			Suspension			82	Side Windows (no chips)	Good		
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	83	Front Wiper Blades	Good		
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good		
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	Wheels and Tyres				
8	Rear Left Indicators	✓	37	CV Joints	✓	61	Left Front	7	85	R/H Mirror	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	62	Right Front	7	86	L/H Mirror	Good		
10	Rear Reflectors	✓	39	Wheel Balance	✓	63	Left Rear	3	87	L/F Guard	Good		
11	Hazard Lights	✓	40	Gearbox (Manual)	•	64	Right Rear	3	88	R/F Guard	Good		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	65	Spare	Yes	89	L/H Doors	Good		
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	✓	90	R/H Doors	Good		
14	Dashboard Dimmer Switch	•	43	Replaced at (odometer reading)		Interior			91	L/H Sill	Good		
15	Number Plate Light	✓	Brakes			67	AC Operation	✓	92	R/H Sill	Good		
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	93	Boot/Tail Gate	Good		
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	94	Front Bumper	Good		
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	95	Rear Bumper	Good		
19	Rev Counter	✓	Keys and Locking			71	Seat Heaters	•	96	Roof	Good		
20	Fuel Gauge	✓	47	Central Locking	✓	72	Sun Visors	✓	97	Bonnet	Good		
21	Wipers Front/Rear	✓	48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓	98	Fuel Cap	✓		
22	Window Opener FL	✓	49	Number of Keys	2	74	Seats	Average	99	Mud Flaps	✓		
23	Window Opener FR	✓	Engine			75	Carpets	Average	100	WOF	✓		
24	Window Opener RL	✓	50	Oil Level	✓	76	Panels	Average					
25	Window Opener RR	✓	51	Smokes and Fumes	✓	77	Dashboard	Average					
26	Rear View Mirrors	✓	52	Performance	✓								
27	Radio (Basic Test Only)	✓	53	Noise	✓								
28	CD (Basic Test Only)	✓	54	Starter Motor	✓								
29	Boot Open Switch	✓											

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	John Lindsay	Date:	09 Jul 2019
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--