



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,544,077
Version:	1
Created:	17 Jul 2019

Make:	Mercedes-Benz	Body Style:	Wagon
Model:	C180	VIN:	WDB2032462F899413
Year:	2007	Odometer:	84,742 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	85	R/H Mirror	Good	86	L/H Mirror	Good	
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	61	Left Front	4	mm	87	L/F Guard	Good		
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		62	Right Front	5	mm	88	R/F Guard	Good	89	L/H Doors	Good
7	Rear Right Indicators	✓	37	CV Joints	✓	63	Left Rear	6	mm	64	Right Rear	4	mm	90	R/H Doors	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	65	Spare	Yes	66	Tools	✓	91	L/H Sill	Good	92	R/H Sill	Good
9	Reversing Lights	✓	39	Wheel Balance	✓	67	AC Operation	✓	68	Heater Fan	✓	93	Boot/Tail Gate	Good	94	Front Bumper	Good
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	69	Seatbelts	✓	70	Horn	✓	95	Rear Bumper	Good	96	Roof	Good
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	71	Seat Heaters	•	72	Sun Visors	✓	97	Bonnet	Good	98	Fuel Cap	✓
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	73	Sun Visors Lights/Mirrors	✓	74	Seats	Average	99	Mud Flaps	✓	100	WOF	✓
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		Interior		75	Carpets	Average	76	Panels	Average	77	Dashboard	Average	
14	Dashboard Dimmer Switch	•	44	Front Brakes	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓
15	Number Plate Light	✓	45	Rear Brakes	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•
16	Dashboard Warning Lights	✓	46	Handbrake	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓
17	Speedo	✓	Keys and Locking		47	Central Locking	✓	70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	
18	Odometer	✓	48	Remote Locking	✓	48	Remote Locking	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Average
19	Rev Counter	✓	49	Number of Keys	1	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	
20	Fuel Gauge	✓	50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓
21	Wipers Front/Rear	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓			
22	Window Opener FL	✓	52	Performance	✓	53	Noise	✓									
23	Window Opener FR	✓	53	Noise	✓												
24	Window Opener RL	✓	54	Starter Motor	✓												
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	✓															
29	Boot Open Switch	✓															

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Kyle Mills-Brown	Date:	17 Jul 2019
<b>I have read and understood this condition guide:</b>			
Name:		Signature:	