



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,544,958
Version:	1
Created:	07 Aug 2019

Make:	Subaru	Body Style:	Wagon
Model:	Exiga	VIN:	7AT0GF1RX19011079
Year:	2010	Odometer:	82,842 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good									
1	Battery	✓	31	Reversing Camera	✓	55	Coolant Condition	✓	79	Sun Roof Operation	✓							
2	Headlights	✓	32	USB Port	✓	56	Performance	✓	80	Front Windscreen (no chips)	Good							
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good							
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓	82	Side Windows (no chips)	Good						
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83	Front Wiper Blades	Good							
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84	Rear Wiper Blade	Good							
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	7.0	mm	85	R/H Mirror	Good				
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	7.0	mm	63	Left Rear	7.0	mm	86	L/H Mirror	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	64	Right Rear	7.0	mm	65	Spare	Yes	66	Tools	✓	87	L/F Guard	Good
10	Rear Reflectors	•	39	Wheel Balance	✓	65	Spare	Yes	66	Tools	✓	88	R/F Guard	Good				
11	Hazard Lights	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓	89	L/H Doors	Good					
12	Courtesy Lights	✓	41	Engine Timing	Cambelt	68	Heater Fan	✓	69	Seatbelts	✓	90	R/H Doors	Good				
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	No	70	Horn	✓	71	Seat Heaters	•	91	L/H Sill	Good				
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	92	R/H Sill	Good				
15	Number Plate Light	✓	Brakes		Interior		67	AC Operation	✓	68	Heater Fan	✓	93	Boot/Tail Gate	Good			
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	69	Seatbelts	✓	94	Front Bumper	Good				
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	70	Horn	✓	95	Rear Bumper	Good				
18	Odometer	✓	46	Handbrake	✓	71	Seat Heaters	•	72	Sun Visors	✓	96	Roof	Good				
19	Rev Counter	✓	Keys and Locking		Interior		70	Horn	✓	73	Sun Visors Lights/Mirrors	✓	97	Bonnet	Good			
20	Fuel Gauge	✓	47	Central Locking	✓	71	Seat Heaters	•	72	Sun Visors	✓	98	Fuel Cap	✓				
21	Wipers Front/Rear	✓	48	Remote Locking	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	99	Mud Flaps	✓				
22	Window Opener FL	✓	49	Number of Keys	2	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	100	WOF	✓				
23	Window Opener FR	✓	Engine		Interior		74	Seats	Good	75	Carpets	Good						
24	Window Opener RL	✓	50	Oil Level	✓	75	Carpets	Good	76	Panels	Good							
25	Window Opener RR	✓	51	Smokes and Fumes	✓	76	Panels	Good	77	Dashboard	Good							
26	Rear View Mirrors	✓	52	Performance	✓													
27	Radio (Basic Test Only)	✓	53	Noise	✓													
28	CD (Basic Test Only)	✓	54	Starter Motor	✓													
29	Boot Open Switch	✓																

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Mathew Varghese	Date:	07 Jul 2019
---------------	-----------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--