

Report ID: 19,545,107 Version: 1 Created: 08 Jul 2019

Make:	Holden	Model:	Cruze	Body Style:	Wagon		Pass	Fail	N/A
Year:	2015	Registration:	JDU695	Reg Expiry:	15 Sep 2019	Engine			L
WoF Expiry:	13 Jun 2020	Odometer:	121,746 Kms	Good No:	19545107	Oil level	~		
VIN:	KL3JA35MJFK024010	Next Service:	134500	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
		_				Performance	V		
Key:	SC	-0	LS		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	~		
R = rust				\prod	THA	Noise	~		
PT = paint defect C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals D SC D D						Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs S P SC D SC W S						Performance			T
Noto come defecte 8 blamiches may not be displayed in the diagram						Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•		
Stonechips on windscreen. Dent in LH and RH sills.						Tyres (lowest observed tread	-		
Water in spare wheel well.						Left front	4		mm
						Right front	4		mm
						Left rear	3		mm
Conditions During Body Inspection: Wet						Right rear	2 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
						Suspension			
Engine has	oil seepage.					Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average			Dashboard warning lights	~				
Dashboa	rd Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Drives ok.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
							1		
Inspected by: Roger King Date: 08 Jul 2019									
I have read and understood this condition guide. Name:									