



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,545,679
Version:	1
Created:	09 Jul 2019

Make:	Mazda	Body Style:	Hatchback
Model:	Atenza	VIN:	7AT0C139X19201877
Year:	2011	Odometer:	98,547 Kms
Road Conditions During Test Drive:	Dry		

Electrical		Transmission and Drive		Cooling System		Exterior	
1	Battery	30	Fuel Flap Release	55	Coolant Condition	78	Under Carriage
2	Headlights	31	Reversing Camera	56	Performance	79	Sun Roof Operation
3	Tail Lights	32	USB Port	57	Radiator/Hoses (visual)	80	Front Windscreen (no chips)
4	High Stop Light	33	Window Lock Switch	58	Suspension Performance	81	Back Windscreen (no chips)
5	Front Right Indicators	34	Operation	59	Steering Performance	82	Side Windows (no chips)
6	Front Left Indicators	35	Noise	60	Shock Absorbers	83	Front Wiper Blades
7	Rear Right Indicators	36	Clutch	61	Left Front	84	Rear Wiper Blade
8	Rear Left Indicators	37	CV Joints	62	Right Front	85	R/H Mirror
9	Reversing Lights	38	Wheel Bearing	63	Left Rear	86	L/H Mirror
10	Rear Reflectors	39	Wheel Balance	64	Right Rear	87	L/F Guard
11	Hazard Lights	40	Gearbox (Manual)	65	Spare	88	R/F Guard
12	Courtesy Lights	41	Engine Timing	66	Tools	89	L/H Doors
13	Dashboard Lights	42	Evidence of Cam Belt Replacement	67	AC Operation	90	R/H Doors
14	Dashboard Dimmer Switch	43	Replaced at (odometer reading)	68	Heater Fan	91	L/H Sill
15	Number Plate Light	44	Front Brakes	69	Seatbelts	92	R/H Sill
16	Dashboard Warning Lights	45	Rear Brakes	70	Horn	93	Boot/Tail Gate
17	Speedo	46	Handbrake	71	Seat Heaters	94	Front Bumper
18	Odometer	47	Central Locking	72	Sun Visors	95	Rear Bumper
19	Rev Counter	48	Remote Locking	73	Sun Visors Lights/Mirrors	96	Roof
20	Fuel Gauge	49	Number of Keys	74	Seats	97	Bonnet
21	Wipers Front/Rear	50	Oil Level	75	Carpets	98	Fuel Cap
22	Window Opener FL	51	Smokes and Fumes	76	Panels	99	Mud Flaps
23	Window Opener FR	52	Performance	77	Dashboard	100	WOF
24	Window Opener RL	53	Noise				
25	Window Opener RR	54	Starter Motor				
26	Rear View Mirrors						
27	Radio (Basic Test Only)						
28	CD (Basic Test Only)						
29	Boot Open Switch						

Turners Certification Key:
 ✓ = Pass
 ✗ = Fail
 • = Not applicable for this vehicle

Inspected by:	John Lindsay	Date:	09 Jul 2019
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--