

Report ID: 19,545,826 Version: 1 Created: 05 Jul 2019

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	<b>Registration:</b>	ERW307	<b>Reg Expiry:</b>	10 Aug 2019	Engine			
WoF Expiry:	06 May 2020	Odometer:	212,147 Kms	Good No:	19545826	Oil level	~		
VIN:	6G1EK55759L182045	Next Service:	221,313kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	PT					Performance	~		
Key:	PILL	-0		S COL		Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent R = rust SSC S						Operation	~		
R = rust PT = paint def				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	PT SC 916			- No	ELE DPT	Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs SC S S S S S S S S S S S S S S S S S S						Performance 🖌			
						Hand Brake	~		
Body inspection Comments						Tyres (lowest observed treat	-	oftvre	
Paint clear coat starting to lift off bonnet & boot spoiler. Stone chips in windscreen.						Left front	· ·	,	mm
						Right front	-		
						Left rear			mm mm
						Right rear		0.0	
Conditions During Body Inspection: Dry							0.0		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Left rear shock Damp, starting to leak.						•			
Lettrear sh	ock Damp, starting to ic					Suspension performance	~		
						Steering performance	~		
						Shock absorbers		~	
						Air Conditioning / Heater			
Interior Comments						Operation Electrical / Accessories	~		
	Good								
Seats						Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	-					Window winder FL	~		
Concret						Window winder FR	~		<u> </u>
<u>General Comments</u> Plastic trim panel on side of drivers seat has a crack in it.						Window winder RL	~		<u> </u>
	parter on side of drivers	scal lias d CidCK				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	Not Applicable	Kms:		Reversing camera			~
Jospostad by Jason Voung									
Inspected by: Jason Young Date: 05 Jul 2019									
I have read and understood this condition guide. Name:									