

Basic Vehicle Condition Guide

Report ID: 19,545,842


Version: 1

Created: 11 Jul 2019

Make: Model: Holden Rodeo 4X2 **Body Style:** Utility Year: 2004 Registration: CDT395 Reg Expiry: 25 Aug 2019 WoF Expiry: **Odometer:** 06 Jun 2020 185,776 Kms **Good No:** 19545842 VIN: MPATFR77H4H53725; Next Service: unknown **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Both wing mirrors broken. Windscreen chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leaks. Powersteering oil leak

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Vent controls broken. LH indicator intermittent fault

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

Hamish McDonald 10 Jul 2019 Inspected by: Date:

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	3		<i>V</i>
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	v v v depth		·
Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	v v v depth		<i>V</i>
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	v v v depth		V
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	v v v depth		<i>V</i>
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	v v v depth		<i>'</i>
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	v v v depth		<i>V</i>
Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	v v v depth		~
Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	v v v depth		<i>'</i>
Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	3		<i>'</i>
Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	3		~
Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	3		<i>V</i>
CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	3		<i>'</i>
Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	3		<i>'</i>
Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	3		
Performance Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	3		
Hand Brake Tyres (lowest observed tread Left front Right front Left rear Right rear	3		
Tyres (lowest observed tread Left front Right front Left rear Right rear	3		
Left front Right front Left rear Right rear	3		\
Right front Left rear Right rear			!S)
Left rear Right rear	3	.0	mm
Right rear		.0	mm
-	2	.0	mm
	2	.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			<u> </u>
Operation		~	
Electrical / Accessories			<u> </u>
Head lights	~		
Tail lights	~		
Indicators		~	
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	v		
Window winder FR	~		
Window winder RL	V		
Window winder RR	·		
Rear view mirrors	· ·		
Radio (basic test only)	~		
CD (basic test only)	<u></u>		
Number of keys	2	<u> </u>	<u> </u>
Central locking	·		
Remote locking		~	
Sat. Nav. (basic test only)			V
- sarrar (Sasie test offy)			<i>v</i>
Reversing camera		1	

I have read and understood this condition guide.

Name:

Signature: