

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V Performance S SC Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent Operation V R = rustNoise V PT = paint defect C = crackClutch V P = pin dent CV joints ~ = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs Performance V Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front mm 3 **Right front** 3 mm Left rear 4.0 mm **Right rear** 4.0 mm Conditions During Body Inspection: Dry Spare N/A Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Average Head lights Seats 1 Tail lights 1 Average Carpets Indicators ~ Average Dashboard warning lights 1 Panels V Wipers (front & rear) Average Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) ~ Number of keys 2

V Central locking Dry Remote locking V

Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable

Inspected by: **Dion Mair**

Road Conditions During Test Drive:

09 Jul 2019 Date:

Sat. Nav. (basic test only)

Reversing camera

Report ID: 19,546,274 Version: 1 Created: 10 Jul 2019

Pass

~

V

V

~

Engine

Oil level

Noise

Smoke & fumes

Performance

N/A

Fail

I have read and understood this condition guide.

Name:

Kms:

Signature:

1

~