

Report ID: 19,597,369 Version: 1 15 Jul 2019 Created:

Make:	Mazda	Model:	MPV2300	Body Style:	SUV][Pass	Fail	N/A
Year:	2005	Registration:	JLE534	Reg Expiry:	31 Oct 2019	Engine			1
WoF Expiry:	22 Nov 2019	Odometer:	115,300 Kms	Good No:	19597369	Oil level	~		
VIN:	7AT0C11EX15441079	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	e. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and ti	nis can be arranged f	or an additional (charge.	Coolant condition	~		
	S SC		S PT SC S SC		S SC	Performance	~		
Key:		=	STISE 55C	5(0)-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
R = rust	s sc			710	E SD	Operation	~		
PT = paint def	ect NP				11111	Noise	~		
C = crack					S SC	Clutch			~
P = pin dent	s sc dl				2414	CV joints	~		
* = decals		10		10	SD SD	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S SC S	C	S SC S D SC		S D	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front 4			mm
						Right front	2	2	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
						Spare Yes			
Under Ca	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)		~	
						Number of keys	2		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism	Timina	Chain			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	r(115;		Reversing camera			~
Inspecte	d by: Donovan Matar	а				Date: 15 Jul 201	9		
	,								

I have read and understood this condition guide.

Name:

Signature: