

Report ID: 19,597,722 Version: 3 21 Aug 2019 Created:

Make:	Hyundai	Model:	130	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2009	<b>Registration:</b>	FEK605	Reg Expiry:	20 Oct 2019	Engine	1		L	
WoF Expiry:	02 Aug 2020	Odometer:	235,715 Kms	Good No:	19597722	Oil level	~			
VIN:	KMHDC51TMAU2209	Next Service:	242,000	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
					Р	Performance	~			
Key:		-0	D SP	-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	- HE			TIN		Operation	~			
R = rust PT = paint def				$\left( \left  \right\rangle \right)$		Noise	~			
C = crack						Clutch	-		~	
P = pin dent					세비	CV joints	~			
* = decals	PSC 916			- NL	ELIP-	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S S S D S P						Performance	~			
		Note: son	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	of tyre	(	
Steering wheel grip cracked						Left front 5.0 mm				
						Right front	4.	-	mm	
						Left rear		-	mm	
						Right rear				
Conditions During Body Inspection: Wet						Spare	6.0 mm			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	V			
Interior Comments						Operation				
Good						Electrical / Accessories Head lights				
Seats						3	~			
Carpets	Good					Tail lights Indicators	~			
	Average						~			
Panels						Dashboard warning lights	<b>v</b>			
Dashboa	rd Good					Wipers (front & rear) Window winder FL	<b>v</b>			
							<b>v</b>			
General (	<u>Comments</u>					Window winder FR Window winder RL	~			
							<b>v</b>			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only) Number of keys			L	
							1			
Road Con	ditions During Test	t Drive:	Dry			Central locking	~			
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
				11113.		Reversing camera			~	
Inspected by: Mathew Varghese Date: 23 Jul 2019										

I have read and understood this condition guide.

Name: .....

Signature: .....