

Report ID: 19,598,360 Version: 4 23 Sep 2019 Created:

Make:	Mazda	Model:	Bt-50	Body Style:	Utility			Pass	Fail	N/A	
Year:	2009	Registration:	HTF648	Reg Expiry:	06 Sep 2019		Engine				
WoF Expiry:	07 Sep 2020	Odometer:	202,231 Kms	Good No:	19598360		Oil level	~			
VIN:	MM0UNY0E40081981	Next Service:	212300	Service Histor	y: No	⅃Ĺ	Smoke & fumes	~			
						٦٢	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged	for an additional c	narge.	Jľ	Coolant condition	~			
	S SC		S SD		S D W	٦Ē	Performance	~			
Key:		-0		501-	300		Radiator / Hoses (visual)	~			
S = scratch	ALE				Tan	lī	Transmission				
D = dent R = rust	S SC W			210	SDW	J	Operation	~			
PT = paint defe		F I		$\left[\left(\right) \right]$	704		Noise	~			
C = crack				$+ \mathbf{\nabla}$	D]	Clutch	-		~	
P = pin dent					세비	T	CV joints	~			
* = decals	s sc 916				ETTR-	1	Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs						ļŀ	Performance	~			
		Note: son	ne defects & blemish	es may not be disn	laved in the diagram		Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram									oftyre))	
Tail light loose and cracked						H	Tyres (lowest observed tread depth of tyres) Left front 8.0				
										mm	
							Right front		.0	mm	
						╡┟	Left rear		.0	mm	
Conditions During Body Inspection: Dry						┛┝	Right rear 8.0			mm	
Under Carriage & Under Bonnet Inspection Comments						٦ŀ	Spare Yes				
	inage & onder bor	metmspectic	<u>on comments</u>				Suspension	1			
							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater				
						٦L	Operation 🖌				
Interior Comments							Electrical / Accessories				
Seats	Poor						Head lights	~			
Carpote	Average						Tail lights	~			
Carpets							Indicators	~			
Panels	Good						Dashboard warning lights	>			
	Good						Wipers (front & rear)	>			
Dashboa	ra						Window winder FL	~			
						╣Ӷ	Window winder FR	~			
General Comments						Window winder RL	~				
Drivers seat	worn						Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						┨┠	Number of keys	1	L	1	
Road Con	ditions During Tes	t Drive [.]	Dry			٦ŀ	Central locking	~			
						┙┟	Remote locking		~		
Engine Timing Mechanism: Cambelt							Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: No Kms:							Reversing camera			~	
L							<u> </u>			1	
Inspected by: Brad Lucas Date: 10 Jul 2019											

I have read and understood this condition guide.

Name:

Signature: