

Report ID: 19,598,696 Version: 2 05 Aug 2019 Created:

Make:	Mini	Model:	Cooper	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	JTR283	Reg Expiry:	28 Oct 2019	Engine			·
WoF Expiry:	01 Jul 2020	Odometer:	130,343 Kms	Good No:	19598696	Oil level	~		
VIN:	WMWRC32040TG7451	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	lis can be arranged to	r an additional C	narge.	Coolant condition	~		
			S SC		S SC	Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	S D SC			10	HIL S	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				TTY .	SC	Clutch	~		
P = pin dent	ssc dl				2416	CV joints	~		
* = decals		10		10	E S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
			S P SC		S P SC	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	6	5	mm
						Right front	6	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		mm
						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
s						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
General Comments Clutch needs adjusting ,						Window winder RL	~		
	is aujusting ,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central							~		
	ning Mashaulau	11				Remote locking	~		
Engine Timing Mechanism: Unknown Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 05 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: