

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

RF inner axle seal has oil seepage. Chassis and parts of cab have surface rust mainly at front end.

			Shock absorbers	~		
			Air Conditioning / Heater			
			Operation	~		
Interior Comments		Electrical / Accessories				
Seats	Average		Head lights	~		
Carpets	Average		Tail lights	~		
			Indicators	~		
Panels	Average		Dashboard warning lights	~		
Dashboard	Average		Wipers (front & rear)	~		
			Window winder FL	~		
			Window winder FR	~		
General Comments			Window winder RL	~		
Drives well		Window winder RR	~			
			Rear view mirrors	~		
			Radio (basic test only)	~		
			CD (basic test only)	~		
			Number of keys	2		
Road Conditions During Test Drive: Dry			Central locking	~		
			Remote locking	~		
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)			~	
Evidence of Can	n Belt Replacement: Not Applicable Kms:		Reversing camera	~		
Inspected by: Roger King				19		

I have read and understood this condition guide.

Name:

Signature:

Report ID: 19,598,762 3 Created: 05 Sep 2019

Version:

Pass

V

V

V

V

V

V

V

V

V

V

V

~

~

7

7

3

1.8

V

V

Yes

Spare

Suspension

Suspension performance

Steering performance

Fail

N/A

V

mm

mm

mm

mm