

Report ID: 19,599,332 Version: 1 23 Jul 2019 Created:

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:	HNQ650	Reg Expiry:	13 Jul 2019	Engine			
WoF Expiry:	22 Jul 2020	Odometer:	69,456 Kms	Good No:	19599332	Oil level	~		
VIN:	JM0DE10Y2D0261130	Next Service:	84450	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and tr	his can be arranged to	r an additional c	narge.	Coolant condition	~		
	SC S		SC S SC			Performance	~		
Key:		-0		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			210	HIV_	Operation	~		
PT = paint def	ect NIP					Noise	~		
C = crack						Clutch	~		
P = pin dent	SDSC DR				24114	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	SC S		S SC S SC	S		Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	3	3	mm
						Right front	3	3	mm
						Left rear	7	7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by Depayan Matara									
Inspected by: Donovan Matara Date: 23 Jul 2019									

I have read and understood this condition guide.

Name:

Signature: