



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,602,009
Version:	2
Created:	16 Sep 2019

Make:	Nissan	Body Style:	SUV
Model:	X-Trail	VIN:	7AT0DH6LX19032331
Year:	2008	Odometer:	97,955 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good		
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation		•				
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good			
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good			
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good					
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	6.0	mm	84	Rear Wiper Blade	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>6.0</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>7.0</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	62	Right Front	6.0	mm	63	Left Rear	7.0	mm	85	R/H Mirror	Good
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>64</td> <td>Right Rear</td> <td>7.0</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	64	Right Rear	7.0	mm	65	Spare	Yes	86	L/H Mirror	Good	
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>66</td> <td>Tools</td> <th>✓<td>87</td><td>L/F Guard</td><td>Good</td></th>	66	Tools	✓ <td>87</td> <td>L/F Guard</td> <td>Good</td>	87	L/F Guard	Good					
10	Rear Reflectors	•	40	Gearbox (Manual)	✓ <th colspan="2">Interior</th> <td>67</td> <td>AC Operation</td> <th>✓<td>88</td><td>R/F Guard</td><td>Good</td></th>	Interior		67	AC Operation	✓ <td>88</td> <td>R/F Guard</td> <td>Good</td>	88	R/F Guard	Good			
11	Hazard Lights	✓ <td>41</td> <td>Engine Timing</td> <td>Timing Chain</td> <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th></th>	41	Engine Timing	Timing Chain	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th>	69	Seatbelts	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good		
12	Courtesy Lights	✓ <td>42</td> <td>Evidence of Cam Belt Replacement</td> <td>Not Applicable</td> <td>70</td> <td>Horn</td> <th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>90</td><td>R/H Doors</td><td>Good</td></th>	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	71	Seat Heaters	•	90	R/H Doors	Good		
13	Dashboard Lights	✓ <td>43</td> <td>Replaced at (odometer reading)</td> <td></td> <td>72</td> <td>Sun Visors</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th></th>	43	Replaced at (odometer reading)		72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>	91	L/H Sill	Good		
14	Dashboard Dimmer Switch	✓ <th colspan="2">Brakes</th> <td>44</td> <td>Front Brakes</td> <th>✓<td>74</td><td>Seats</td><td>Good</td><td>92</td><td>R/H Sill</td><td>Good</td></th>	Brakes		44	Front Brakes	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	74	Seats	Good	92	R/H Sill	Good			
15	Number Plate Light	✓ <td>45</td> <td>Rear Brakes</td> <th>✓<td>46</td><td>Handbrake</td><th>✓<td>75</td><td>Carpets</td><td>Good</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th></th>	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>75</td><td>Carpets</td><td>Good</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>	46	Handbrake	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	75	Carpets	Good	93	Boot/Tail Gate	Good		
16	Dashboard Warning Lights	✓ <th colspan="2">Keys and Locking</th> <td>47</td> <td>Central Locking</td> <th>✓<td>76</td><td>Panels</td><td>Good</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	Keys and Locking		47	Central Locking	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	76	Panels	Good	94	Front Bumper	Good			
17	Speedo	✓ <td>48</td> <td>Remote Locking</td> <th>✓<td>49</td><td>Number of Keys</td><td>1</td><td>77</td><td>Dashboard</td><td>Good</td><td>95</td><td>Rear Bumper</td><td>Good</td></th>	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td>	49	Number of Keys	1	77	Dashboard	Good	95	Rear Bumper	Good		
18	Odometer	✓ <th colspan="2">Engine</th> <td>50</td> <td>Oil Level</td> <th>✓<td colspan="2"></td><td>78</td><td>Fuel Cap</td><th>✓<td>96</td><td>Roof</td><td>Good</td></th></th>	Engine		50	Oil Level	✓ <td colspan="2"></td> <td>78</td> <td>Fuel Cap</td> <th>✓<td>96</td><td>Roof</td><td>Good</td></th>			78	Fuel Cap	✓ <td>96</td> <td>Roof</td> <td>Good</td>	96	Roof	Good	
19	Rev Counter	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>52</td><td>Performance</td><th>✓<td colspan="2"></td><td>97</td><td>Bonnet</td><td>Good</td></th></th>	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td colspan="2"></td><td>97</td><td>Bonnet</td><td>Good</td></th>	52	Performance	✓ <td colspan="2"></td> <td>97</td> <td>Bonnet</td> <td>Good</td>			97	Bonnet	Good			
20	Fuel Gauge	✓ <td>53</td> <td>Noise</td> <th>✓<td>54</td><td>Starter Motor</td><th>✓<td colspan="2"></td><td>98</td><td>Fuel Cap</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th></th>	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td colspan="2"></td><td>98</td><td>Fuel Cap</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th>	54	Starter Motor	✓ <td colspan="2"></td> <td>98</td> <td>Fuel Cap</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th>			98	Fuel Cap	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓
21	Wipers Front/Rear	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td>100</td> <td>WOF</td> <th>✓</th>									100	WOF	✓			
22	Window Opener FL	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td>														
23	Window Opener FR	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td>														
24	Window Opener RL	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td>														
25	Window Opener RR	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td>														
26	Rear View Mirrors	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td>														
27	Radio (Basic Test Only)	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td>														
28	CD (Basic Test Only)	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td>														
29	Boot Open Switch	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td>														

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Ca Thach	Date:	11 Jul 2019
---------------	----------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--