

Report ID: 19,602,680 Version: 1 16 Jul 2019 Created:

Make:	LDV	Model:	G10	Body Style:	People Mover		Pass	Fail	N/A
Year:	2016	Registration:	KGD303	Reg Expiry:	30 Jun 2019	Engine			L
WoF Expiry:		Odometer:	59,949 Kms	Good No:	19602680	Oil level	~		
VIN:	LSKG4AL19FA422407	Next Service:	68000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	pration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	SC		SP			Performance	~		
Key:	La C	-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	sc A			210	HIVS	Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack						Clutch			~
P = pin dent	sc				24114	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significan	SC		S			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
L mirror body cracked						Tyres (lowest observed tread depth of tyres)			es)
L repeater cracked						Left front	7.8 mn		mm
						Right front	7.	6	mm
						Left rear	3.	1	mm
Conditions During Body Inspection: Dry						Right rear	2.9 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Very dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
	ning Masharitar	الما			 	Remote locking	~		
-	ming Mechanism:	Unknow		K.		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Stuart Melbourne Date: 16 Jul 2019									
Date: 10 Jul 2019									

I have read and understood this condition guide.

Name:

Signature: