



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,603,210
Version:	3
Created:	08 Nov 2019

Make:	Suzuki	Body Style:	Hatchback
Model:	Splash	VIN:	TSMEXB32S00176911
Year:	2008	Odometer:	64,940 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good					
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good					
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good			
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	85	R/H Mirror	Good	86	L/H Mirror	Good			
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		87	L/F Guard	Good	88	R/F Guard	Good			
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	7	mm	62	Right Front	7	mm	89	L/H Doors	Good			
7	Rear Right Indicators	✓	37	CV Joints	✓	63	Left Rear	3	mm	64	Right Rear	4	mm	90	R/H Doors	Good			
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	65	Spare	Yes	66	Tools	✓	Interior		67	AC Operation	✓			
9	Reversing Lights	✓	39	Wheel Balance	✓	68	Heater Fan	•	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•		
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good		
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	76	Panels	Good	77	Dashboard	Good	78	Seats	Good	79	CD (Basic Test Only)	✓		
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	80	WOF	✓	81	WOF	✓	82	WOF	✓	83	WOF	✓		
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		84	WOF	✓	85	WOF	✓	86	WOF	✓	87	WOF	✓		
14	Dashboard Dimmer Switch	•	Brakes		44	Front Brakes	✓	45	Rear Brakes	✓	46	Handbrake	✓	Keys and Locking		47	Central Locking	✓	
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	Keys and Locking		47	Central Locking	✓	48	Remote Locking	✓	49	Number of Keys	1
16	Dashboard Warning Lights	✓	46	Handbrake	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓
17	Speedo	✓	Keys and Locking		47	Central Locking	✓	48	Remote Locking	✓	49	Number of Keys	1	Engine		50	Oil Level	✓	
18	Odometer	✓	48	Remote Locking	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓		
19	Rev Counter	✓	49	Number of Keys	1	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓					
20	Fuel Gauge	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓
21	Wipers Front/Rear	✓	50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓		
22	Window Opener FL	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓					
23	Window Opener FR	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓								
24	Window Opener RL	✓	53	Noise	✓	54	Starter Motor	✓											
25	Window Opener RR	✓	54	Starter Motor	✓														
26	Rear View Mirrors	✓																	
27	Radio (Basic Test Only)	✓																	
28	CD (Basic Test Only)	✓																	
29	Boot Open Switch	✓																	

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Neil Honeyman	Date:	08 Nov 2019
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--