

Basic Vehicle Condition Guide

Report ID: 19,603,234


Version: 1

Created: 15 Jul 2019

Make: Model: **Body Style:** SUV Toyota Highlander Year: 2008 Registration: HFF492 Reg Expiry: 26 Aug 2019 **Odometer:** WoF Expiry: **Good No:** 11 Jun 2020 187,224 Kms 19603234 VIN: **Next Service:** JTEES41A902083670 192800 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Surface rust in inner Tailgate area, Stone chips on roof gone rusty,

Conditions During Body Inspection: Wet

<u>Under Carriage & Under Bonnet Inspection Comments</u>
/

Interior Comment	<u>S</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Good

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Chris Buckley

	Pass	Fail	N/A		
Engine Engine	rass	Ган	IN/A		
Oil level	.,				
Smoke & fumes					
	<i>V V</i>				
Performance	•				
Noise	•				
Cooling System					
Coolant condition	<i>V</i>				
Performance	<i>V</i>				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes			T		
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	4.0		mm		
Right front	5.0		mm		
Left rear	4.0		mm		
Right rear	4.0		mm		
Spare Yes					
Suspension					
Suspension performance	~				
Steering performance	V V				
Shock absorbers	~				
Air Conditioning / Heater		!			
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	\(\times \)				
Wipers (front & rear)					
Window winder FL	V V				
Window winder FR	~				
Window winder RL	·				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)	~				
Number of keys	3				
Central locking	<i>y</i>				
Remote locking	<i>v</i>				
			./		
Sat. Nav. (basic test only)			V		

Reversing camera

15 Jul 2019

I have read and understood this condition guide. Name: Signature: