

Report ID: 19,603,275 Version: 1 12 Jul 2019 Created:

| Make: | Ford | Model: | Focus | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|---|----------------------|------------------------|--------------------|----------------------|---|------|------|-----|
| Year: | 2007 | Registration: | EFM480 | Reg Expiry: | 02 Jan 2020 | Engine | • | | • |
| WoF Expiry: | 06 Jun 2020 | Odometer: | 157,496 Kms | Good No: | 19603275 | Oil level | ~ | | |
| VIN: | WF05XXGCD57J4656 | Next Service: | | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a quide only. Conside | eration is made | for age and mileage | . Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | lical inspection prior to | purchase and ti | his can be arranged to | or an additional o | narge. | Coolant condition | ~ | | |
| | | | S | | | Performance | V | | |
| Key: | | = | | 5(0)- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust | sc | | | 20 | HILLS | Operation | ~ | | |
| PT = paint def | ect NP | | | | 11111 | Noise | V | | |
| C = crack | | | | | SC | Clutch | ~ | | |
| P = pin dent | s sc dP | | | | 74116 | CV joints | ~ | | |
| * = decals | | 10 | | 10 | | Wheel bearings | V | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| | SC W | e | | | S P | Performance | ~ | | |
| Body Insr | pection Comments | Note: son | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Stonechips on windscreen. RH headlamp has moisture. | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Both rear indicators not orange. Remote locking not working. | | | | | | Left front 5 r | | | mm |
| | | | | | | Right front | | 5 | mm |
| | | | | | | Left rear | | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | | 6 m | |
| | | | | | Spare | Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | Suspension | | | | |
| Both rear sv | waybar links are worn. | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | r | | |
| | | | | | | Shock absorbers | r | | |
| | | | | | | Air Conditioning / Heater | 1 | | 1 |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | 1 | I | 1 |
| Seats | Average | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | , verage | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | Average | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ird | | | | | Window winder FL | ~ | | |
| | 1 | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| Drives ok. | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | I | 1 |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | | ~ | |
| Engine Ti | ming Mechanism: | Timing (| Chain | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | 1 | 1 |
| Inspecte | d by: Roger King | | | | | Date: 12 Jul 201 | 9 | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: