

Report ID: 19,603,313 Version: 1 19 Jul 2019 Created:

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2011	<b>Registration:</b>	GCQ606	<b>Reg Expiry:</b>	26 Oct 2019	Engine		I		
WoF Expiry:	20 Aug 2019	Odometer:	106,600 Kms	Good No:	19603313	Oil level	~			
VIN:	JM0DE10Y2C0220446	Next Service:	110354	Service Histor	<b>y:</b> Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:	P SC	-0	SC W S SC	-01-	w	Radiator / Hoses (visual)	~			
S = scratch						Transmission			1	
D = dent R = rust	s sc w			715	S PT W	Operation	~			
PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HID				74114	CV joints	~			
* = decals	sc 916			- Jul	ELD SC	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S W S SC W SC W						Performance	~			
		Note: son	ne defects & blemishes	mav not be disc	laved in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread	•	oftvre	es)	
						Right front	-	. <i>7</i> .8	mm	
						Left rear		.0 .2	mm	
Canditiana Duvina Dadukana atian. D						Right rear			 mm	
Conditions During Body Inspection: Dry						Right rear 6.5 mm   Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	ody inspection complete					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	V			
						Operation				
Interior Comments						Electrical / Accessories	· · · · · · · · · · · · · · · · · · ·			
Good Good						Head lights				
Jeals						Tail lights	~			
Carpets	Good					Indicators	v v			
Dam - I-	Good					Dashboard warning lights	~ ~			
Panels						Wipers (front & rear)	~ ~			
Dashboa	rd Good					Window winder FL	v v			
						Window winder FL	<i>v</i> <i>v</i>			
General Comments						Window winder RL				
						Window winder RL	~ ~			
						Rear view mirrors	<i>v</i> <i>v</i>			
						Radio (basic test only) CD (basic test only)	~ ~		+	
						Number of keys			<u> </u>	
						Central locking	2			
Road Conditions During Test Drive: Dry						-				
Engine Tir	ming Mechanism:	Timing (	Chain			Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
						Reversing camera			~	
Inspected	Inspected by: Melissa Haggerty Date: 19 Jul 2019									
L										

I have read and understood this condition guide.

Name: .....

Signature: .....