

Report ID: 19,605,648 Version: 1 15 Jul 2019 Created:

Signature:

Make:	Nissan	Model:	Maxima	Body Style:	Sedan		Pass	Fail	N/A
Year:	1999	Registration:	XQ5309	Reg Expiry:	10 Jan 2020	Engine			
WoF Expiry:	24 Oct 2019	Odometer:	165,000 Kms	Good No:	19605648	Oil level	~		
VIN:	JN1CCUA32A0021213	Next Service:	169000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S D R PT W		S D PT S D PT		S D	Performance	~		
Key:	SDRPI	-0	SDPI SDPI	$- \square$	<u>ISD</u>	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S PT SC W D S D PT W						Operation	~		
PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	S R PT SC	Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	DRPTSC 91			-No-	BIN SDR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SDPT W SDPT W SDPT W SDW						Performance		~	
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~	•	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftvre) 25)
Driver side monsoon missing Aerial wand snapped off									mm
Rear centre light cover cracks						Right front			mm
Boot alignment						Left rear			
						4 mm			
Conditions During Body Inspection: Dry						-			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Radio volume nob missing and display broken									
Seats stained						Suspension performance	~		
Engine oil le	eak					Steering performance Shock absorbers	~		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation Electrical / Accessories	~		
driver seat worn and compartment ripped									
Seats		· · · · ·				Head lights	~		
Carpets	stains					Tail lights	~		
<u> </u>	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Ganaral	ommonts					Window winder FR	~		
General Comments Brakes squeaking					Window winder RL	~			
Gear chang						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Tim	ning Machanisme	T:	Chain			Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Increate	d by: John Lindsov					Date: 15 Jul 201	0		
Inspected by: John Lindsay Date: 15 Jul 2019									

I have read and understood this condition guide.

Name: