



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,606,801
Version:	1
Created:	13 Aug 2019

Make:	Nissan	Body Style:	SUV
Model:	Dualis	VIN:	7AT0DH7HX19207711
Year:	2009	Odometer:	99,088 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good				
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	5.0	mm	86	L/H Mirror	Good					
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>5.0</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	5.0	mm	87	L/F Guard	Good					
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>5.0</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	5.0	mm	88	R/F Guard	Good					
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>5.0</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	5.0	mm	89	L/H Doors	Good					
10	Rear Reflectors	•	40	Gearbox (Manual)	•	65	Spare	Yes	66	Tools	✓	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓	68	Heater Fan	✓	91	L/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	69	Seatbelts	✓	70	Horn	✓	92	R/H Sill	Good			
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		71	Seat Heaters	•	72	Sun Visors	✓	93	Boot/Tail Gate	Good			
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good				
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	75	Carpets	Good	76	Panels	Good			
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓	77	Dashboard	Good	78	WOF	✓				
17	Speedo	✓	48	Remote Locking	•	49	Number of Keys	1	79	Fuel Cap	✓	80	Mud Flaps	✓			
18	Odometer	✓	Engine		50	Oil Level	✓	81	Smokes and Fumes	✓	82	Performance	✓	83	Noise	✓	
19	Rev Counter	✓	51	Starter Motor	✓	52	CV Joints	✓	84	Clutch	✓	85	Wheel Bearing	✓	86	Wheel Balance	✓
20	Fuel Gauge	✓	53	CV Joints	✓	54	Wheel Bearing	✓	87	Wheel Balance	✓	88	CV Joints	✓	89	Wheel Bearing	✓
21	Wipers Front/Rear	✓	55	CV Joints	✓	56	Wheel Bearing	✓	90	CV Joints	✓	91	Wheel Bearing	✓	92	CV Joints	✓
22	Window Opener FL	✓	57	CV Joints	✓	58	Wheel Bearing	✓	93	CV Joints	✓	94	CV Joints	✓	95	CV Joints	✓
23	Window Opener FR	✓	59	CV Joints	✓	60	Wheel Bearing	✓	96	CV Joints	✓	97	CV Joints	✓	98	CV Joints	✓
24	Window Opener RL	✓	61	CV Joints	✓	62	Wheel Bearing	✓	99	CV Joints	✓	100	CV Joints	✓	101	CV Joints	✓
25	Window Opener RR	✓	63	CV Joints	✓	64	Wheel Bearing	✓	102	CV Joints	✓	103	CV Joints	✓	104	CV Joints	✓
26	Rear View Mirrors	✓	65	CV Joints	✓	66	Wheel Bearing	✓	105	CV Joints	✓	106	CV Joints	✓	107	CV Joints	✓
27	Radio (Basic Test Only)	✓	67	CV Joints	✓	68	Wheel Bearing	✓	108	CV Joints	✓	109	CV Joints	✓	110	CV Joints	✓
28	CD (Basic Test Only)	✓	69	CV Joints	✓	70	Wheel Bearing	✓	111	CV Joints	✓	112	CV Joints	✓	113	CV Joints	✓
29	Boot Open Switch	✓	71	CV Joints	✓	72	Wheel Bearing	✓	114	CV Joints	✓	115	CV Joints	✓	116	CV Joints	✓

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Ca Thach	Date:	16 Jul 2019
---------------	----------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--