



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,606,926
Version:	1
Created:	16 Jul 2019

Make:	Nissan	Body Style:	SUV
Model:	Dualis	VIN:	7AT0DH7HX19200339
Year:	2008	Odometer:	109,416 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good								
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	✓	80	Front Windscreen (no chips)	Good								
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good								
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58 <td>Suspension Performance</td> <th>✓</th> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	Suspension Performance	✓	83	Front Wiper Blades	Good									
4	High Stop Light	✓	Transmission and Drive		34 <td>Operation</td> <th>✓</th> <td>59</td> <td>Steering Performance</td> <th>✓</th> <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	Operation	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good									
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		85	R/H Mirror	Good									
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	7	mm	86	L/H Mirror	Good										
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	7	mm	87	L/F Guard	Good										
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	63	Left Rear	7	mm	88	R/F Guard	Good										
9	Reversing Lights	✓	39	Wheel Balance	✓	64	Right Rear	7	mm	89	L/H Doors	Good										
10	Rear Reflectors	✓	40	Gearbox (Manual)	• <td>65</td> <td>Spare</td> <td>Yes</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	65	Spare	Yes	90	R/H Doors	Good											
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	91	L/H Sill	Good											
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	Interior		67 <td>AC Operation</td> <th>✓</th> <td>92</td> <td>R/H Sill</td> <td>Good</td>	AC Operation	✓	92	R/H Sill	Good									
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓	69	Seatbelts	✓	93	Boot/Tail Gate	Good								
14	Dashboard Dimmer Switch	✓	Brakes		44 <td>Front Brakes</td> <th>✓</th> <td>70</td> <td>Horn</td> <th>✓</th> <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	Front Brakes	✓	70	Horn	✓	71	Seat Heaters	•	94	Front Bumper	Good						
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	95	Rear Bumper	Good					
16	Dashboard Warning Lights	✓	Keys and Locking		47 <td>Central Locking</td> <th>✓</th> <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	Central Locking	✓	74	Seats	Good	75	Carpets	Good	96	Roof	Good						
17	Speedo	✓	48	Remote Locking	✓	49	Number of Keys	2	76	Panels	Good	77	Dashboard	Good	97	Bonnet	Good					
18	Odometer	✓	Engine		50 <td>Oil Level</td> <th>✓</th> <td>51</td> <td>Smokes and Fumes</td> <th>✓</th> <td>52</td> <td>Performance</td> <th>✓</th> <td>53</td> <td>Noise</td> <th>✓</th> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	98	Fuel Cap	✓			
19	Rev Counter	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Reversing Camera	✓	99	Mud Flaps	✓		
20	Fuel Gauge	✓	53	Noise	✓	54	Starter Motor	✓	55	Reversing Camera	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	100	WOF	✓		
21	Wipers Front/Rear	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	Turners Certification Key:				
22	Window Opener FL	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	7	mm	62	Right Front	7	mm	63	Left Rear	7	mm	✓ = Pass	
23	Window Opener FR	✓	61	Left Front	7	mm	62	Right Front	7	mm	63	Left Rear	7	mm	64	Right Rear	7	mm	65	Spare	Yes	✗ = Fail
24	Window Opener RL	✓	62	Right Front	7	mm	63	Left Rear	7	mm	64	Right Rear	7	mm	65	Spare	Yes	66	Tools	✓	• = Not applicable for this vehicle	
25	Window Opener RR	✓	63	Left Rear	7	mm	64	Right Rear	7	mm	65	Spare	Yes	66	Tools	✓	67	AC Operation	✓			
26	Rear View Mirrors	✓	64	Right Rear	7	mm	65	Spare	Yes	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓				
27	Radio (Basic Test Only)	✓	65	Spare	Yes	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓					
28	CD (Basic Test Only)	✓	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓					
29	Boot Open Switch	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•					
			68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓					
			69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓					
			70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good					
			71	Seat Heaters	•	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good					
			72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good					
			73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good					
			74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good								
			75	Carpets	Good	76	Panels	Good	77	Dashboard	Good											
			76	Panels	Good	77	Dashboard	Good														
			77	Dashboard	Good																	

Inspected by:	Xinghui Lin	Date:	16 Jul 2019
I have read and understood this condition guide:			
Name:		Signature:	