

Basic Vehicle Condition Guide

Report ID: 19,607,159


Version: 1

Created: 19 Jul 2019

Make: Model: SUV Toyota Landcruiser Prado **Body Style:** Year: 2013 Registration: HAJ12 Reg Expiry: 20 Apr 2020 WoF Expiry: **Odometer: Good No:** 12 Mar 2020 146,154 Kms 19607159 VIN: Next Service: 153000 JTEBH3FJ60K110182 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Average			
Panels	Average			
Dashboard	Good			

General Comments

Inspected by:

4wd

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

Bobby Zhong

Kms:

Name:

	Pass	Fail	N/A					
Fngine	1 033	ı all	19/74					
Engine Oil level								
Smoke & fumes	•							
Performance	\(\times \)							
	./							
Cooling System Coolant condition								
Performance								
Radiator / Hoses (visual)								
Transmission	•							
Operation								
Noise	•							
Clutch	_							
CV joints Wheel bearings	•							
Brakes		<u> </u>						
Performance								
	-							
Hand Brake	l donth	of ture) s)					
Tyres (lowest observed tread depth of tyres) Left front 4 mm								
		4	mm					
Right front Left rear		5	mm					
		7	mm					
Right rear		5	mm					
Spare Suspension		Yes						
Suspension performance								
Steering performance	<i>V</i>							
Shock absorbers	•							
Air Conditioning / Heater	•							
Operation								
Electrical / Accessories								
Head lights	•/							
Tail lights	•							
Indicators	~							
Dashboard warning lights	•							
Wipers (front & rear)	<i>'</i>							
Window winder FL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \							
Window winder FR	<i>y</i>							
Window winder RL	~							
Window winder RR	~							
Rear view mirrors		~						
Radio (basic test only)	~	+						
CD (basic test only)	~							
Number of keys	2	L	<u> </u>					
Central locking	<i>V</i>							
Remote locking	~	-						
Sat. Nav. (basic test only)	_		-					
Reversing camera	V		-					
g camera								

19 Jul 2019

Signature:

Date:

have road	and und	arctand th	is condition	s auida