

Report ID: 19,608,083 Version: 2 19 Aug 2019 Created:

Make:	Toyota	Model:	Liteace	Body Style:	Van		Pass	Fail	N/A
Year:	2009	Registration:	KKA234	Reg Expiry:	15 Aug 2019	Engine			
WoF Expiry:	08 Feb 2020	Odometer:	101,415 Kms	Good No:	19608083	Oil level	~		
VIN:	7AT0H60JX17011239	Next Service:	111415	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	W		S SC W SC		S SC	Performance	~		
Key:		-0	S SC W SC	$- \square$	330	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	Fransmission		
D = dent R = rust				215	S SC	Operation	~		
PT = paint defe		F		$\left[\left(\right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	Decimination				74 <u>11</u>	CV joints	~		
* = decals	PSCW			The second	BID SSC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W SC S SC S SC W SC						Performance	~		
Body Incr	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
						Left front 8.6 m			mm
						Right front	ç)	mm
						Left rear	5.		mm
Conditions During Body Inspection: Dry						Right rear	9.9 m		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No underbo	ody inspection complet	ed				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Wear and	tear. small hole o	on each front seats			Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central							~		
						Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by Melics Haggerty									
Inspected by: Melissa Haggerty Date: 19 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: