

Report ID: 19,608,335 Version: 1 24 Jul 2019 Created:

Make:	Mitsubishi	Model:	Colt	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	Registration:	DZH260	Reg Expiry:	01 Jan 2020	Engine			·
WoF Expiry:	10 May 2020	Odometer:	173,361 Kms	Good No:	19608335	Oil level	~		
VIN:	7A8CJ0X0707204590	Next Service:	183000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	<u>s</u>	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s sc			715	SC W	Operation	~		
PT = paint defe	ect NP	r I		$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	sc dle			$\langle \rangle$	74116	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – signincan			SC			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	0	mm
						Right front	5.	0	mm
						Left rear	7.	0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		
						Spare	oare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
	_					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments Engine hard to start when cold					Window winder RL	~			
Engine naro						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ming Machanisme	Timina	- 			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Chris Vanner Date: 18 Jul 2019									

I have read and understood this condition guide.

Name: