

Basic Vehicle Condition Guide

Report ID: 19,608,645

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Coolant condition Performance

Radiator / Hoses (visual)

19 Jul 2019 Created:

Pass

1

1

/

V

1

V

6.5

mm

Tyres (lowest observed tread depth of tyres)


N/A

Fail

Make: Great Wall Model: V-Series **Body Style:** Utility Year: 2010 Registration: FME625 **Reg Expiry:** 21 Oct 2019 WoF Expiry: **Odometer:** 05 Jun 2020 93,957 Kms **Good No:** 19608645 VIN: LGWDB3179AB602949 Next Service: 101965 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RL reflector light crack Stone chips on the windscreen FR seat switch cover insecure

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

AC compressor drive belt crack Underbody major surface rust

Excessive oil leak around engine and transmission area

Interior Comments

Seats	FR and FL seat worn
Carpets	Average
Panels	Average
Dashboard	steering wheel worn

General Comments

Drive belt noisy on idle Steering wheel noisy Exhaust pipe leak

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms:

Right front 6.5 mm Left rear 7.5 mm Right rear 7.5 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR 1 Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera 1 19 Jul 2019 Date:

Inspected by:	Sudhin Ramachandran
I have read and u	understood this condition guide.