

Report ID: 19,609,269 Version: 2 01 Aug 2019 Created:

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2016	Registration:	JYR603	Reg Expiry:	18 Oct 2019	Engine	1		L
WoF Expiry:	30 Jul 2020	Odometer:	101,354 Kms	Good No:	19609269	Oil level	~		
VIN:	MM0DJ2HAA0W2128:	Next Service:	110188	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
					S	Performance	~		
Key:	S	-0	s s			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc			715	HILS	Operation	~		
PT = paint defe		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	sc 616			-NG		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Podulaci		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
Stone chips on the windscreen						Left front 4 mm			
						Right front	4		mm
						Left rear	3.		mm
Conditions During Body Inspection: Dry						Right rear	3.8 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
L						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	duod					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	-		
						Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Sudhin Ramachandran Date: 01 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: