



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,609,282
Version:	1
Created:	30 Jul 2019

Make:	Mazda	Body Style:	Hatchback
Model:	Verisa	VIN:	7AT0C103X19343557
Year:	2010	Odometer:	90,986 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good	
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		85	R/H Mirror	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	5.5	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	5.5	mm	87	L/F Guard	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	63	Left Rear	5.8	mm	88	R/F Guard	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓	64	Right Rear	6.5	mm	89	L/H Doors	Good		
10	Rear Reflectors	•	40	Gearbox (Manual)	•	65	Spare	Yes	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	91	L/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	Interior		67	AC Operation	✓	92	R/H Sill	Good	
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓	93	Boot/Tail Gate	Good			
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	69	Seatbelts	✓	94	Front Bumper	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓	70	Horn	✓	95	Rear Bumper	Good			
16	Dashboard Warning Lights	✓	46	Handbrake	✓	71	Seat Heaters	•	96	Roof	Good			
17	Speedo	✓	Keys and Locking		47	Central Locking	✓	72	Sun Visors	✓	97	Bonnet	Good	
18	Odometer	✓	48	Remote Locking	✓	49	Number of Keys	1	73	Sun Visors Lights/Mirrors	✓	98	Fuel Cap	✓
19	Rev Counter	✓	Engine		50	Oil Level	✓	74	Seats	Good	99	Mud Flaps	✓	
20	Fuel Gauge	✓	51	Smokes and Fumes	✓	52	Performance	✓	75	Carpets	Good	100	WOF	✓
21	Wipers Front/Rear	✓	53	Noise	✓	54	Starter Motor	✓	76	Panels	Good			
22	Window Opener FL	✓							77	Dashboard	Good			
23	Window Opener FR	✓												
24	Window Opener RL	✓												
25	Window Opener RR	✓												
26	Rear View Mirrors	✓												
27	Radio (Basic Test Only)	✓												
28	CD (Basic Test Only)	✓												
29	Boot Open Switch	✓												

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Sudhin Ramachandran	Date:	19 Jul 2019
I have read and understood this condition guide:			
Name:		Signature:	