



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,611,447
Version:	1
Created:	07 Aug 2019

Make:	Honda	Body Style:	
Model:	CRV	VIN:	7AT08G7HX19103479
Year:	2008	Odometer:	110,727 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	85	R/H Mirror	Good	86	L/H Mirror	Good	
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		87	L/F Guard	Good	88	R/F Guard	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	1.5	mm	89	L/H Doors	Good	90	R/H Doors	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	3.0	mm	91	L/H Sill	Good	92	R/H Sill	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	63	Left Rear	3.0	mm	93	Boot/Tail Gate	Good	94	Front Bumper	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓	64	Right Rear	4.5	mm	95	Rear Bumper	Good	96	Roof	Good		
10	Rear Reflectors	•	40	Gearbox (Manual)	•	65	Spare	Yes	66	Tools	✓	97	Bonnet	Good	98	Fuel Cap	✓
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓	68	Heater Fan	✓	99	Mud Flaps	✓	100	WOF	✓
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	69	Seatbelts	✓	70	Horn	✓						
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		71	Seat Heaters	•	72	Sun Visors	✓						
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	Interior		73	Sun Visors Lights/Mirrors	✓					
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	74	Seats	Good						
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓	75	Carpets	Good							
17	Speedo	✓	48	Remote Locking	✓	49	Number of Keys	2	76	Panels	Good						
18	Odometer	✓	Engine		50	Oil Level	✓	77	Dashboard	Good							
19	Rev Counter	✓	51	Smokes and Fumes	✓	52	Performance	✓									
20	Fuel Gauge	✓	53	Noise	✓	54	Starter Motor	✓									
21	Wipers Front/Rear	✓															
22	Window Opener FL	✓															
23	Window Opener FR	✓															
24	Window Opener RL	✓															
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	✓															
29	Boot Open Switch	✓															

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:
✓ = Pass
X = Fail
• = Not applicable for this vehicle

Inspected by:	Ca Thach	Date:	22 Jul 2019
I have read and understood this condition guide:			
Name:		Signature:	