

Report ID: 19,611,633 Version: 1 06 Aug 2019 Created:

Make:	Fiat	Model:	Grande Punto	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	Registration:		Reg Expiry:	10 Feb 2020	Engine			L
WoF Expiry:		Odometer:	143,960 Kms	Good No:	19611633	Oil level	~		
VIN:	ZFA19900001333332	Next Service:		Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	Danta harra nat	harry discovered and an	Noise	· ·		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	SC SC	-161-	D SC W	Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		L
D = dent	sc 6/6			TIN	SC W	Operation	~		
R = rust PT = paint def				\int	JHIH	Noise	~		
C = crack				+		Clutch	~		
P = pin dent					세비	CV joints	~		
* = decals	sc 916			-No-	HIP	Wheel bearings	~		
SC = stone chi		26		1al	\mathbb{X}	Brakes	•		L
W = significant scuffs SC SC SC SC SC SC SC						Performance	~		
		Note: son	ne defects & blemishes	mav not be disc	laved in the diagram	Hand Brake	~		
Body Inst	pection Comments			, ,	, ,	Tyres (lowest observed tread	•	of tyre	<u> </u>
· ·					Left front 5.0 mm				
						Right front		.0	mm
						Left rear		.0	mm
Condition	as During Padulas	naction	Mat			Right rear	-		 mm
Conditions During Body Inspection: Wet						Right rear 8.0 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	1	L
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
							1	1	L
Inspecte	d by: Chris Vanner					Date: 19 Jul 201	9		

I have read and understood this condition guide.

Name:

Signature: