

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V Performance Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent S Operation V R = rustNoise V PT = paint defect C = crackClutch V P = pin dent CV joints ~ SC \* = decals PT Wheel bearings V SC = stone chips Brakes W = significant scuffs SC Performance V Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front mm 5 **Right front** 5 mm Left rear 6 mm **Right rear** 6 mm Conditions During Body Inspection: Dry Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories WORN APPEARANCE Head lights Seats 1 Tail lights ~ OK Carpets Indicators ~ OK Dashboard warning lights 1 Panels Wipers (front & rear) 1 OK Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) V Number of keys 1 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism: Timing Chain** Sat. Nav. (basic test only) V Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera ~ 01 Oct 2019 Inspected by: Roger King Date:

I have read and understood this condition guide.

Name: .....

Report ID: 19,611,772 Version: 3 Created: 01 Oct 2019

Pass

~

V

V

~

Engine

Oil level

Noise

Smoke & fumes

Performance

N/A

Fail