

Basic Vehicle Condition Guide

Report ID: 19,614,616

Pass

1

V

/

V

1

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 02 Aug 2019

Fail

N/A

1

mm

mm

mm

 mm

4.0

5.0

5.0

5.0

1

/

/

1

/


2

Yes

Make: Subaru Model: Legacy **Body Style:** Sedan Year: 2006 Registration: **DJC593 Reg Expiry:** 24 May 2020 **WoF Expiry: Odometer:** 18 Apr 2020 197,215 Kms **Good No:** 19614616 VIN: JF1BL5KS56G022232 **Next Service:** 200000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Chris Vanner

I have read and understood this condition guide.

Evidence of Cam Belt Replacement: No

	Remote locking	V			
	Sat. Nav. (basic test only)			~	
Kms:	Reversing camera			~	
Date: 24 Jul 2019					
Name: Signature:				••••••	