

Report ID: 19,615,173 Version: 1 23 Jul 2019 Created:

| Make: | Ford | Model: | Laser | Body Style: | Sedan | | Pass | Fail | N/A |
|--|--------------------------|--------------------|------------------------|---------------------------------------|----------------------|------------------------------|---------|---------|-----|
| Year: | 1997 | Registration: | ZH6778 | Reg Expiry: | 17 Aug 2019 | Engine | | | |
| WoF Expiry: | 25 Aug 2019 | Odometer: | 269,129 Kms | Good No: | 19615173 | Oil level | ~ | | |
| VIN: | 7A86G0M0700300388 | Next Service: | 0 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismontled or | Noise | V | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | |
| | | | | | S SC | Performance | ~ | | |
| Key: | S D SC | -0 | S P SC S D SC | | SSC | Radiator / Hoses (visual) | ~ | | |
| S = scratch | STE | | | NG G | <u>کھر</u> | Transmission | | | L |
| D = dent R = rust | SDCSC | | | 715 | S D C SC | Operation | ~ | | |
| PT = paint def | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | S SC | Clutch | | | ~ |
| P = pin dent | HID | | | | ᅰᇉ | CV joints | ~ | | |
| * = decals | S D PT SC 91 | | | -No- | S SC | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significan | S D PT SC S | | S D SC S P SC | | S P SC | Performance | ~ | | |
| Dashulasa | <u></u> | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| BODY INS | pection Comments | | | | | Tyres (lowest observed tread | d depth | of tyre | es) |
| | | | | | | Left front 6 m | | | |
| | | | | | | Right front | | , 7 | mm |
| | | | | | | Left rear | | 5 | mm |
| Conditions During Rody Inspections | | | | | | Right rear | | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Minor oil le | ak,minor underneath bo | ody surface rust , | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | - | | |
| | | | | | | Operation | | ~ | |
| Interior Comments | | | | | | Electrical / Accessories | I | - | L |
| Seats | drivers sea | t ripped,wear an | d tear,minor stains , | | | Head lights | ~ | | |
| | woor and t | ear,minor stains | | | | Tail lights | ~ | | |
| Carpets | | car,minor stains | 1 | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | | h cracked | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | h cracked , | | | | Window winder FL | ~ | | |
| | 1 | | | | I | Window winder FR | ~ | | |
| <u>General</u> (| <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 3 | I | 1 |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | | | ~ |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lo | Kms: | | Reversing camera | | | ~ |
| | | | | | | - | | 1 | |
| Inspecte | d by: Donovan Matar | a | | | | Date: 23 Jul 201 | 9 | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: