



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,615,435
Version:	1
Created:	24 Jul 2019

Make:	Mitsubishi	Body Style:	SUV
Model:	Outlander	VIN:	7AT0CJ3MX19102457
Year:	2006	Odometer:	123,406 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	
4	High Stop Light	✓	Transmission and Drive		Wheels and Tyres		59	Steering Performance	✓	60	Shock Absorbers	✓	85	R/H Mirror	Good		
5	Front Right Indicators	✓	34	Operation	✓	61	Left Front	5	mm	62	Right Front	4	mm	86	L/H Mirror	Good	
6	Front Left Indicators	✓	35	Noise	✓	63	Left Rear	3	mm	64	Right Rear	4	mm	87	L/F Guard	Good	
7	Rear Right Indicators	✓	36	Clutch	•	65	Left Rear	3	mm	66	Right Rear	4	mm	88	R/F Guard	Good	
8	Rear Left Indicators	✓	37	CV Joints	✓	67	Left Rear	4	mm	68	Right Rear	4	mm	89	L/H Doors	Good	
9	Reversing Lights	✓	38	Wheel Bearing	✓	69	Left Rear	3	mm	70	Right Rear	4	mm	90	R/H Doors	Good	
10	Rear Reflectors	✓	39	Wheel Balance	✓	71	Left Rear	3	mm	72	Right Rear	4	mm	91	L/H Sill	Good	
11	Hazard Lights	✓	40	Gearbox (Manual)	•	73	Left Rear	3	mm	74	Right Rear	4	mm	92	R/H Sill	Good	
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	75	Left Rear	3	mm	76	Right Rear	4	mm	93	Boot/Tail Gate	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	77	Left Rear	3	mm	78	Right Rear	4	mm	94	Front Bumper	Good	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		79	Left Rear	3	mm	80	Right Rear	4	mm	95	Rear Bumper	Good	
15	Number Plate Light	✓	Brakes		Interior		81	Left Rear	3	mm	82	Right Rear	4	mm	96	Roof	Good
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	83	Left Rear	3	mm	84	Right Rear	4	mm	97	Bonnet	Good	
17	Speedo	✓	45	Rear Brakes	✓	85	Left Rear	3	mm	86	Right Rear	4	mm	98	Fuel Cap	✓	
18	Odometer	✓	46	Handbrake	✓	87	Left Rear	3	mm	88	Right Rear	4	mm	99	Mud Flaps	✓	
19	Rev Counter	✓	Keys and Locking		Wheels and Tyres		89	Left Rear	3	mm	90	Right Rear	4	mm	100	WOF	✓
20	Fuel Gauge	✓	47	Central Locking	✓	91	Left Rear	3	mm	92	Right Rear	4	mm				
21	Wipers Front/Rear	✓	48	Remote Locking	✓	93	Left Rear	3	mm	94	Right Rear	4	mm				
22	Window Opener FL	✓	49	Number of Keys	1	95	Left Rear	3	mm	96	Right Rear	4	mm				
23	Window Opener FR	✓	Engine		Interior		97	Left Rear	3	mm	98	Right Rear	4	mm			
24	Window Opener RL	✓	50	Oil Level	✓	99	Left Rear	3	mm	100	Right Rear	4	mm				
25	Window Opener RR	✓	51	Smokes and Fumes	✓		Left Front	5	mm		Right Front	4	mm				
26	Rear View Mirrors	✓	52	Performance	✓		Left Rear	3	mm		Right Rear	4	mm				
27	Radio (Basic Test Only)	✓	53	Noise	✓		Left Rear	3	mm		Right Rear	4	mm				
28	CD (Basic Test Only)	✓	54	Starter Motor	✓		Left Rear	3	mm		Right Rear	4	mm				
29	Boot Open Switch	✓					Left Rear	3	mm		Right Rear	4	mm				

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

#### Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Bobby Zhong	Date:	24 Jul 2019
---------------	-------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--