



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,615,442
Version:	1
Created:	02 Aug 2019

Make:	Subaru	Body Style:	Wagon
Model:	Exiga	VIN:	7AT0GF1RX19011206
Year:	2012	Odometer:	92,677 Kms
Road Conditions During Test Drive:	Dry		

Electrical			Cooling System			Exterior		
1	Battery	✓	30	Fuel Flap Release	✓	78	Under Carriage	Good
2	Headlights	✓	31	Reversing Camera	•	79	Sun Roof Operation	•
3	Tail Lights	✓	32	USB Port	✓	80	Front Windscreen (no chips)	Good
4	High Stop Light	✓	33	Window Lock Switch	✓	81	Back Windscreen (no chips)	Good
5	Front Right Indicators	✓	Transmission and Drive			82	Side Windows (no chips)	Good
6	Front Left Indicators	✓	34	Operation	✓	83	Front Wiper Blades	Good
7	Rear Right Indicators	✓	35	Noise	✓	84	Rear Wiper Blade	Good
8	Rear Left Indicators	✓	36	Clutch	•	85	R/H Mirror	Good
9	Reversing Lights	✓	37	CV Joints	✓	86	L/H Mirror	Good
10	Rear Reflectors	•	38	Wheel Bearing	✓	87	L/F Guard	Good
11	Hazard Lights	✓	39	Wheel Balance	✓	88	R/F Guard	Good
12	Courtesy Lights	✓	40	Gearbox (Manual)	•	89	L/H Doors	Good
13	Dashboard Lights	✓	41	Engine Timing	Cambelt	90	R/H Doors	Good
14	Dashboard Dimmer Switch	✓	42	Evidence of Cam Belt Replacement	No	91	L/H Sill	Good
15	Number Plate Light	✓	43	Replaced at (odometer reading)		92	R/H Sill	Good
16	Dashboard Warning Lights	✓	Brakes			93	Boot/Tail Gate	Good
17	Speedo	✓	44	Front Brakes	✓	94	Front Bumper	Good
18	Odometer	✓	45	Rear Brakes	✓	95	Rear Bumper	Good
19	Rev Counter	✓	46	Handbrake	✓	96	Roof	Good
20	Fuel Gauge	✓	Keys and Locking			97	Bonnet	Good
21	Wipers Front/Rear	✓	47	Central Locking	✓	98	Fuel Cap	✓
22	Window Opener FL	✓	48	Remote Locking	✓	99	Mud Flaps	✓
23	Window Opener FR	✓	49	Number of Keys	2	100	WOF	✓
24	Window Opener RL	✓	Engine			Turners Certification Key: ✓ = Pass X = Fail • = Not applicable for this vehicle		
25	Window Opener RR	✓	50	Oil Level	✓			
26	Rear View Mirrors	✓	51	Smokes and Fumes	✓			
27	Radio (Basic Test Only)	✓	52	Performance	✓			
28	CD (Basic Test Only)	✓	53	Noise	✓			
29	Boot Open Switch	✓	54	Starter Motor	✓			
			55	Coolant Condition	✓			
			56	Performance	✓			
			57	Radiator/Hoses (visual)	✓			
			Suspension					
			58	Suspension Performance	✓			
			59	Steering Performance	✓			
			60	Shock Absorbers	✓			
			Wheels and Tyres					
			61	Left Front	6.5 mm			
			62	Right Front	6.5 mm			
			63	Left Rear	4.8 mm			
			64	Right Rear	5.0 mm			
			65	Spare	Yes			
			66	Tools	✓			
			Interior					
			67	AC Operation	✓			
			68	Heater Fan	✓			
			69	Seatbelts	✓			
			70	Horn	✓			
			71	Seat Heaters	•			
			72	Sun Visors	✓			
			73	Sun Visors Lights/Mirrors	✓			
			74	Seats	Good			
			75	Carpets	Good			
			76	Panels	Good			
			77	Dashboard	Good			

Inspected by:	Sudhin Ramachandran	Date:	24 Jul 2019
I have read and understood this condition guide:			
Name:		Signature:	