

Basic Vehicle Condition Guide

Report ID: 19,617,199


Version: 2

Created: 28 Jul 2019

Make: Model: Holden Rodeo 4X2 **Body Style:** Utility Year: 2005 Registration: FTU95 **Reg Expiry:** 24 Aug 2019 WoF Expiry: **Odometer:** 08 Feb 2020 372,733 Kms **Good No:** 19617199 VIN: MPATFR77H5H580732 Next Service: 370,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chip on front windscreen

1 key remote not working

RH tail lamp cracked

Rear number plate lights not working, wiring needs attention

Wina mirrors not working properly

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak Transmission oil leak Steering rack boot leak Rear wheel drive

Interior Comme	<u>nts</u>
Seats	Good
Carpets	Average
Panels	Average
Dachbaard	Good

General Comments

Dashboard

AC blower speeds 1&2 not working . AC not getting cold

Reverse camera needs to be aligned

ABS light not coming on

Brake need attention, spongy and holding after releasing the brake.

Vehicle not getting started and engine light flashes sometimes

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

28 Jul 2019 Inspected by: Mathew Varghese Date:

Name:

	Pass	Fail	N/A	
Engine	•	•		
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints			~	
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front 7				
Right front	7		mm	
Left rear	7		mm	
Right rear	6		mm	
Spare	Yes			
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation		~		
Electrical / Accessories	l			
Head lights	~			
Tail lights		~		
Indicators	~			
Dashboard warning lights		~		
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	\(\triangle \)			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors		~		
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	~			
Remote locking	1			
Sat. Nav. (basic test only)			·	
Reversing camera	~		Ť	
l	1	1	1	

Signature: