

Report ID: 19,618,396 Version: 1 29 Jul 2019 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2005		CQC289	Reg Expiry:	20 Aug 2019	Engine			L
WoF Expiry:		Odometer:	234,086 Kms	Good No:	19618396	Oil level	~		
VIN:	6G1ZK54B55L386331	Next Service:	- ,	Service Histor		Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		6 1 1			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	SC W	-0	S S		SP	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	ISC 6/6				S PT	Operation	~		
R = rust PT = paint def					JHIH	Noise	~		
C = crack			-	+	SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	s sc gig				EIRS	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC W S S S S S S S						Performance	~		T
					layed in the diagram	Hand Brake	~		
	pection Comments	<u>-</u>					•	ofture	
RH number plate lamp not going. Paint damage on rear bumper. Stonechips on windscreen. Glovebox stops						Tyres (lowest observed tread depth of tyres)			
damaged.Consul lid catch broken.Roof lining coming off. Pockets on rear of both front seats are damaged.Gear shift boot damaged. Wear on RF seat and steering wheel. Buttons damaged on steering						Left front	6		mm
wheel						Right front	6		mm
						Left rear	4		mm
Conditions During Body Inspection: Wet						Right rear	5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	-	•		aaalay kaaa kaa ail		Suspension			
Bonnet gas	struts not working. Eng	gine has oli seepa	ge. Power steering	cooler nose has oli	seepage.	Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Average						Electrical / Accessories			T
Seats	Avelage					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		<u> </u>
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
CD player not loading cds.					Window winder RR	~			
Drives ok .						Rear view mirrors	~		
						Radio (basic test only)	2		
						CD (basic test only)		~	
						Number of keys	3		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
•	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							-		
Inspecte	d by: Roger King					Date: 29 Jul 201	9		

I have read and understood this condition guide.

Name:

Signature: