



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| | |
|------------|-------------|
| Report ID: | 19,618,884 |
| Version: | 1 |
| Created: | 02 Aug 2019 |

| | | | |
|------------------------------------|--------|-------------|-------------------|
| Make: | Mazda | Body Style: | Sedan |
| Model: | Atenza | VIN: | 7AT0C139X19202114 |
| Year: | 2011 | Odometer: | 35,248 Kms |
| Road Conditions During Test Drive: | Dry | | |

| Electrical | | | Cooling System | | | Exterior | | |
|------------|--------------------------|---|------------------------|----------------------------------|----------------|--|-----------------------------|------|
| 1 | Battery | ✓ | 30 | Fuel Flap Release | ✓ | 78 | Under Carriage | Good |
| 2 | Headlights | ✓ | 31 | Reversing Camera | ✓ | 79 | Sun Roof Operation | • |
| 3 | Tail Lights | ✓ | 32 | USB Port | • | 80 | Front Windscreen (no chips) | Good |
| 4 | High Stop Light | ✓ | 33 | Window Lock Switch | ✓ | 81 | Back Windscreen (no chips) | Good |
| 5 | Front Right Indicators | ✓ | Transmission and Drive | | | 82 | Side Windows (no chips) | Good |
| 6 | Front Left Indicators | ✓ | 34 | Operation | ✓ | 83 | Front Wiper Blades | Good |
| 7 | Rear Right Indicators | ✓ | 35 | Noise | ✓ | 84 | Rear Wiper Blade | Good |
| 8 | Rear Left Indicators | ✓ | 36 | Clutch | • | 85 | R/H Mirror | Good |
| 9 | Reversing Lights | ✓ | 37 | CV Joints | ✓ | 86 | L/H Mirror | Good |
| 10 | Rear Reflectors | • | 38 | Wheel Bearing | ✓ | 87 | L/F Guard | Good |
| 11 | Hazard Lights | ✓ | 39 | Wheel Balance | ✓ | 88 | R/F Guard | Good |
| 12 | Courtesy Lights | ✓ | 40 | Gearbox (Manual) | • | 89 | L/H Doors | Good |
| 13 | Dashboard Lights | ✓ | 41 | Engine Timing | Timing Chain | 90 | R/H Doors | Good |
| 14 | Dashboard Dimmer Switch | ✓ | 42 | Evidence of Cam Belt Replacement | Not Applicable | 91 | L/H Sill | Good |
| 15 | Number Plate Light | ✓ | 43 | Replaced at (odometer reading) | | 92 | R/H Sill | Good |
| 16 | Dashboard Warning Lights | ✓ | Brakes | | | 93 | Boot/Tail Gate | Good |
| 17 | Speedo | ✓ | 44 | Front Brakes | ✓ | 94 | Front Bumper | Good |
| 18 | Odometer | ✓ | 45 | Rear Brakes | ✓ | 95 | Rear Bumper | Good |
| 19 | Rev Counter | ✓ | 46 | Handbrake | ✓ | 96 | Roof | Good |
| 20 | Fuel Gauge | ✓ | Keys and Locking | | | 97 | Bonnet | Good |
| 21 | Wipers Front/Rear | ✓ | 47 | Central Locking | ✓ | 98 | Fuel Cap | ✓ |
| 22 | Window Opener FL | ✓ | 48 | Remote Locking | • | 99 | Mud Flaps | ✓ |
| 23 | Window Opener FR | ✓ | 49 | Number of Keys | 2 | 100 | WOF | ✓ |
| 24 | Window Opener RL | ✓ | Engine | | | Turners Certification Key: ✓ = Pass X = Fail • = Not applicable for this vehicle | | |
| 25 | Window Opener RR | ✓ | 50 | Oil Level | ✓ | | | |
| 26 | Rear View Mirrors | ✓ | 51 | Smokes and Fumes | ✓ | | | |
| 27 | Radio (Basic Test Only) | ✓ | 52 | Performance | ✓ | | | |
| 28 | CD (Basic Test Only) | ✓ | 53 | Noise | ✓ | | | |
| 29 | Boot Open Switch | ✓ | 54 | Starter Motor | ✓ | | | |
| | | | | | | | | |
| | | | 55 | Coolant Condition | ✓ | | | |
| | | | 56 | Performance | ✓ | | | |
| | | | 57 | Radiator/Hoses (visual) | ✓ | | | |
| | | | Suspension | | | | | |
| | | | 58 | Suspension Performance | ✓ | | | |
| | | | 59 | Steering Performance | ✓ | | | |
| | | | 60 | Shock Absorbers | ✓ | | | |
| | | | Wheels and Tyres | | | | | |
| | | | 61 | Left Front | 4.0 mm | | | |
| | | | 62 | Right Front | 4.0 mm | | | |
| | | | 63 | Left Rear | 4.0 mm | | | |
| | | | 64 | Right Rear | 4.0 mm | | | |
| | | | 65 | Spare | Yes | | | |
| | | | 66 | Tools | ✓ | | | |
| | | | Interior | | | | | |
| | | | 67 | AC Operation | ✓ | | | |
| | | | 68 | Heater Fan | ✓ | | | |
| | | | 69 | Seatbelts | ✓ | | | |
| | | | 70 | Horn | ✓ | | | |
| | | | 71 | Seat Heaters | • | | | |
| | | | 72 | Sun Visors | ✓ | | | |
| | | | 73 | Sun Visors Lights/Mirrors | ✓ | | | |
| | | | 74 | Seats | Good | | | |
| | | | 75 | Carpets | Good | | | |
| | | | 76 | Panels | Good | | | |
| | | | 77 | Dashboard | Good | | | |

| | | | |
|---|-----------------|------------|-------------|
| Inspected by: | Mathew Varghese | Date: | 29 Jul 2019 |
| I have read and understood this condition guide: | | | |
| Name: | | Signature: | |