

Report ID: 19,619,258 Version: 3 23 Aug 2019 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	HPU605	Reg Expiry:	10 Feb 2020	Engine			
WoF Expiry:		Odometer:	101,694 Kms	Good No:	19619258	Oil level	~		
VIN:	WBAVA76000NL3619	Next Service:	Just Serviced	Service Histor	y: No	Smoke & fumes	~		
Netes This was						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan		purchase and t	nis can be analiged ic		Lilaige.	Coolant condition	~		
						Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	s AR			10	SC SC	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	HP				24Ub	CV joints	~		
* = decals	- die	20		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
		- C			SC	Performance	~		
Body Inst	ection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	4	.0	mm
						Right front	4	.0	mm
						Left rear	8	.0	mm
Conditions During Body Inspection: Dry						Right rear	8.0 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil lea	ak					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	5 -					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
·						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Dion Mair Date: 12 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: