

Report ID: 19,621,157 Version: 1 30 Jul 2019 Created:

Make:	Suzuki	Model:	Kizashi	Body Style:	Sedan		Pass	Fail	N/A
Year:	2012	Registration:	GPU581	Reg Expiry:	08 Oct 2019	Engine	1		L
WoF Expiry:	14 Dec 2019	Odometer:	84,649 Kms	Good No:	19621157	Oil level	~		
VIN:	JSAFRE91S00120371	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and tr	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S		S S		S	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sc			10	Ell Is	Operation	~		
PT = paint def	ect NP	1				Noise	~		
C = crack						Clutch			~
P = pin dent	HE				74HL	CV joints	~		
* = decals	- die	10		10		Wheel bearings	۲		
SC = stone chips W = significant scuffs						Brakes			
			S S	S	S	Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
RL tyre inner edge wear						Tyres (lowest observed tread depth of tyres)			
Front headlamps dull						Left front	4.	.6	mm
						Right front	5.	.6	mm
						Left rear	2.	.8	mm
Conditions During Body Inspection: Dry						Right rear	3.8 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonts						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Cood					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
Ganaral	Comments					Window winder FR	~		<u> </u>
						Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Ti	ming Mechanism:	Timina				Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
Lvidence		Ciriciit. N	lot Applicable	11115.		Reversing camera			~
Inspecte	d by: Sudhin Ramach	andran				Date: 30 Jul 201	9		

I have read and understood this condition guide.

Name:

Signature: