

Report ID: 19,622,825 Version: 3 30 Nov 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	Registration:	HCJ36	Reg Expiry:	30 Apr 2020	Engine			
WoF Expiry:	26 Nov 2020	Odometer:	188,800 Kms	Good No:	19622825	Oil level	~		
VIN:	VSKCVND40A0528031	Next Service:	191000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	S S			Radiator / Hoses (visual)	~		-
S = scratch						Transmission			
D = dent R = rust	s dla			715	HIL	Operation	~		
PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HID				게	CV joints	~		
* = decals	- Alf			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant	scutts		S S	JUS		Performance	~		
Rodylace	oction Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		+
body inspection comments						Tyres (lowest observed tread depth of tyres)			
Stone chips on the windscreen Rear canopy door gas strut weak						Left front 8.5 m			mm
						Right front	8.	.5	mm
						Left rear	8.		mm
Conditions During Body Inspection: Dry						Right rear			mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4WD						Suspension performance	~		
Spare tyre ri	m rusty					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
	, Average					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		1
	I					Window winder FR	~		1
General Comments						Window winder RL	~		1
						Window winder RR	~		1
						Rear view mirrors	~		1
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		1
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		<u> </u>
		. 2000.	****			Remote locking	~		+
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Greg Morgan Date: 22 Nov 2019									

I have read and understood this condition guide.

Name: