

Report ID: 19,622,904 Version: 1 02 Aug 2019 Created:

Make:	Toyota	Model:	Harrier	Body Style:	SUV		Pass	Fail	N/A
Year:	2005	Registration:	HTP798	Reg Expiry:	16 Aug 2019	Engine			
WoF Expiry:	10 Jan 2020	Odometer:	175,247 Kms	Good No:	19622904	Oil level	~		
VIN:	7AT0H634X14011034	Next Service:		Service Histor	y: No	Smoke & fumes	~		1
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and ti	his can be arranged fo	or an additional of	charge.	Coolant condition	~		
	S				S	Performance	~		
Key:	L. L	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	SC A			710	HIV	Operation	~		
PT = paint defe	ect NP				17111	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7414	CV joints	~		
* = decals	sc 916			To .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan						Performance	~		
Body Incr	Dection Commonts	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		<u> </u>
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front 5			
						Right front	5	5	mm
						Left rear		2	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
Conditions During Body inspection. Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil le	eaks					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
	, dash crack	red				Wipers (front & rear)	~		<u> </u>
Dashboa	rd					Window winder FL	~		<u> </u>
	I					Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		<u> </u>
2wd						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		1
						Number of keys	1		L
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		† ·
L									1
Inspected	d by: Bobby Zhong					Date: 02 Aug 20	19		

I have read and understood this condition guide.

Name:

Signature: