

Report ID: 19,623,687 Version: 1 12 Aug 2019 Created:

Make:	Mercedes-Benz	Model:	C280 Elegance	Body Style:	Sedan		Pass	Fail	N/A
Year:	1994	Registration:	MHD472	Reg Expiry:	27 Sep 2019	Engine			
WoF Expiry:	03 Feb 2020	Odometer:	171,461 Kms	Good No:	19623687	Oil level	~		
VIN:		Next Service:	,	Service Histor	y: No	Smoke & fumes	~		
						Performance	•	~	
	port is not a warranty		6	- Danta harra nat	harry alternatively at an	Noise	~	•	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	sc	-0	PT	-01-	РТ	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			715	HIL S	Operation	~		
R = rust PT = paint def				\int		Noise	~		
C = crack				+	PT	Clutch			~
P = pin dent	H	2 1		$ \downarrow $	세비	CV joints			~
* = decals	PT SC 9			The	ALC PT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs PT		S		S	Performance	~		
Dedulae		Note: som	ne defects & blemishe	es may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemisnes may not be displayed in the diagram						Tyres (lowest observed tread depth of tyres)			
									mm
						Right front	6		mm
						Left rear			mm
Conditions During Body Inspection: Wet						Right rear	-		mm
Conditions During Body inspection. Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation			~
Interior Comments						Electrical / Accessories			I
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Cuts out are	ound 2000 revs					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Con	ditions During Te	st Drive:	Wet			Central locking		~	
	-					Remote locking		~	
-	ming Mechanism:	-	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Repla	cement: N	lot Applicable	Kms:		Reversing camera			~
									•
Inspected by: Stuart Melbourne Date: 12 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: