

Report ID: 19,623,976 Version: 1 07 Aug 2019 Created:

Make:	Honda	Model:	CRV	Body Style:	SUV		Pass	Fail N/A
Year:	2007		LNF567	Reg Expiry:	24 Jul 2019	Engine		
WoF Expiry:	08 May 2020	Odometer:	123,662 Kms	Good No:	19623976	Oil level	~	
VIN:	7AT08G7HX18012276	Next Service:	130000	Service Histor	y: No	Smoke & fumes	~	
					-	Performance	~	
	port is not a warranty		C 1 11	D		Noise	~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System		
						Coolant condition		
						Performance	~	
Key:		-0	LS	-161-		Radiator / Hoses (visual)	~	
S = scratch						Transmission		
						Operation	~	
R = rust PT = paint defe				\prod		Noise	~	
C = crack				+		Clutch		~
P = pin dent					세비	CV joints	~	
* = decals	sc 916			- AL	ETTPS-	Wheel bearings	~	
SC = stone chips						Brakes		
W = significan	t scuffs	$-\emptyset$				Performance	~	
		Note: som	he defects & blemishe	s may not be disr	laved in the diagram	Hand Brake	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Tyres (lowest observed tread depth of tyres)	
						Right front	5.0	mm
						Left rear	5.0	-
					Right rear	6.0 mm		
Conditions During Body Inspection: Dry						-	6.0 mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension		
	rear bushes starting to					Suspension performance	~	
201101 01111						Steering performance	~	
						Shock absorbers	~	
						Air Conditioning / Heater	V	
						Operation	~	
Interior Comments						Electrical / Accessories		
	Average					Head lights		
Seats							~	
Carpets	Average					Tail lights	~	
	Average					Indicators	~	
Panels						Dashboard warning lights	~	
Dashboa	rd Average					Wipers (front & rear) Window winder FL	~	
							~	
General (<u>Comments</u>					Window winder FR	~	
	<u>connents</u>					Window winder RL	~	
						Window winder RR	~	
						Rear view mirrors	~	
						Radio (basic test only)	~	
						CD (basic test only)	~	
L						Number of keys	2	
Road Conditions During Test Drive: Dry						Central locking	~	
Engine Ti	ning Mechanism:	Timing				Remote locking	~	
						Sat. Nav. (basic test only)		~
Lvidence		ement. N	lot Applicable	11115.		Reversing camera		~
Inspected by: Greg Morgan Date: 01 Aug 2019								

I have read and understood this condition guide.

Name:

Signature: