

Report ID: 19,624,336 Version: 4 29 Aug 2019 Created:

Make:	Mini	Model:	Cooper	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2007		MDD794	Reg Expiry:	18 Sep 2019	Engine			
WoF Expiry:		Odometer:	85,080 Kms	Good No:	19624336	Oil level	~		
VIN:	WMWMF72030TV002			Service History		Smoke & fumes	~		
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		,. 110	Performance	~		
	port is not a warranty					Noise	~		+
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
		_				Performance	~		+
Key:		-0			SP	Radiator / Hoses (visual)	<i>v</i> <i>v</i>		
S = scratch						Transmission			
									T
R = rust				10		Operation Noise	-		
PT = paint defe	ect 1			+			~		+
C = crack P = pin dent	LHC					Clutch			~
* = decals	sc dr				ENR	CV joints	~		
SC = stone chips						Wheel bearings	5		
W = significant scuffs						Brakes			<u>т </u>
						Performance	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
One of the keys doesn't lock on remote						Tyres (lowest observed tread depth of tyres)			
Boot release switch rubber torn						Left front		2	mm
						Right front		4	mm
						Left rear		2	mm
Conditions During Body Inspection: Dry						Right rear	2 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
D!!	Good					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
с						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors		V	
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
			•			Remote locking		~	1
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
						_		1	<u> </u>
Inspected by: Mathew Varghese Date: 29 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: