

Report ID: 19,625,226 Version: 1 12 Aug 2019 Created:

Make:	Hyundai	Model:	120	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:		Reg Expiry:	29 Sep 2019	Engine			
WoF Expiry:	30 Sep 2019	Odometer:	72,200 Kms	Good No:	19625226	Oil level	~		
VIN:	MALBB51CMEM59290	Next Service:		Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting is mode	for any and miles as	Dauta hava nat	heen dispendentied or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	s w	-0	S D PT S D	-	S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	D PT SC W			The	HILS	Operation	~		
PT = paint defe				$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	LANG HID				74 <u>11</u>	CV joints	~		
* = decals DRSC 919 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W S D S D W S D						Performance		~	
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Right rear door trim loose						Tyres (lowest observed tread depth of tyres)			
Nghtrear door thin loose						Left front 3 m			mm
						Right front	4	1	mm
						Left rear	e	5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Brakes wori	า					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	driver seat	stains and worn				Head lights	~		
	carpet wo	'n				Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 12 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: