


<b>Make:</b>	Nissan	<b>Model:</b>	Teana	<b>Body Style:</b>	Sedan
<b>Year:</b>	2004	<b>Registration:</b>	GY505	<b>Reg Expiry:</b>	27 Dec 2019
<b>WoF Expiry:</b>	16 Feb 2020	<b>Odometer:</b>	141,647 Kms	<b>Good No:</b>	19626533
<b>VIN:</b>	7AT0DH71X13101347	<b>Next Service:</b>		<b>Service History:</b>	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs


**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

RH indicator repeater lamp has moisture. LH mirror body broken. LR wheel center cap missing. Stonechips on windscreen.  
Park brake light not working in dash. 2x RH air vents in dash are damaged. Wear on seat cloth, all seats.

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments**

Coolant additive concentration below manufactures recommended level suggest coolant change. Engine has oil seepage. Engine splash guard held with cable ties RHS.

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

**General Comments**

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	5	mm	
Right front	5	mm	
Left rear	4	mm	
Right rear	3	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Roger King

Date: 06 Aug 2019

I have read and understood this condition guide.

Name: .....

Signature: .....